

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Monday, December 20, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Franklin County</b>	STA 13030+00 – 13063+00 MVP-FR-289 MVP-FR-290	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |  |  |  |   |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching           | <input type="checkbox"/> Stringing/Welding  |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-H1, S-G26, S-G27, W-RR4, S-RR18, W-KL41 and S-RR16.

**Routine Maintenance:** (*72-Hour Deadline from Notification*)

- STA 13043+00: SSF maintenance needed.
- STA 13043+50: P1 maintenance needed.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Monday, December 20, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, December 20, 2021

**Figure 1: STA 13043+00 – SSF maintenance needed.**

BRG: 286°W (T) LAT: 37.127931 LON: -80.116535 ±16ft ALT: 2685ft



**Figure 2: STA 12043+50 – P1 maintenance needed.**

BRG: 313°NW (T) LAT: 37.128038 LON: -80.116263 ±1502ft ALT: 2678ft



**Figure 3: STA 13060+00 – Controls in place and functioning properly.**

BRG: 95°E (T) LAT: 37.127169 LON: -80.112077 ±32ft ALT: 2723ft



**Figure 4: STA 13047+00 – Controls in place and functioning properly.**

BRG: 69°E (T) LAT: 37.143696 LON: -80.118512 ±9429ft ALT: 2710ft

