

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, December 17, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13575+21 – 13644+82	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II6, S-GH4 and S-E28.

**Routine Maintenance:** (*72-Hour Deadline from Notification*)

- STA 13577+00: Re-stabilize area.
- STA 13627+00: Re-stabilize area.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Friday, December 17, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, December 17, 2021

**Figure 1: STA 13577+50 – Re-stabilization needed.**

BRG: 264°W (T) LAT: 37.092890 LON: -79.979329 ±16ft ALT: 1370ft



**Figure 2: STA 13587+00 – Controls in place and functioning properly.**

BRG: 246°SW (T) LAT: 37.092251 LON: -79.979316 ±541ft ALT: 1333ft



**Figure 3: STA 13611+00 – Controls in place and functioning properly.**

BRG: 105°E (T) LAT: 37.094025 LON: -79.968093 ±213ft ALT: 1314ft



**Figure 4: STA 13627+50 – Re-stabilization needed.**

BRG: 103°E (T) LAT: 37.089560 LON: -79.965701 ±164ft ALT: 1071ft

