

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, December 16, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12866+36 – 12915+20 MVP-RO-286	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ12, W-MN7-PEM, W-LK51-PSS, S-KL55, W-KL49-PEM, W-KL50, W-KL48-PSS, S-ST9b and W-EF46.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, December 16, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, December 16, 2021

Figure 1: STA 12910+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 184°S (T) LAT: 37.135368 LON: -80.136183 ±17762ft ALT: 2723ft



Figure 2: STA 12896+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 212°SW (T) LAT: 37.148069 LON: -80.134009 ±32ft ALT: 2624ft



Figure 3: STA 12892+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 220°SW (T) LAT: 37.149909 LON: -80.133341 ±328ft ALT: 2737ft



Figure 4: STA 12881+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 45°NE (T) LAT: 37.148881 LON: -80.119800 ±10121ft ALT: 2659ft

