

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, December 14, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12690+00 – 12730+00 MVP-RO-280 MVP-RO-281	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-Y13 and S-Y14.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, December 14, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, December 14, 2021

Figure 1: STA 12701+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 302°NW (T) LAT: 37.190745 LON: -80.153811 ±16ft ALT: 3353ft



Figure 2: STA 12725+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 114°SE (T) LAT: 37.185484 LON: -80.149804 ±16ft ALT: 3397ft



Figure 3: STA 12710+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 144°SE (T) LAT: 37.188799 LON: -80.151953 ±164ft ALT: 2997ft



Figure 4: STA 12705+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 149°SE (T) LAT: 37.190526 LON: -80.153287 ±164ft ALT: 3341ft

