

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, February 1, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13892+45 – 14009+86 MVP-FR-306.02/306.03	Weather:	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II2, S-CD1, W-CD1, W-EF48, S-KL35, S-KL36 and S-KL38.

**Ineffective Controls:** (24-Hour Deadline from Notification)

- STA 13948+00: SSF repair needed.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Tuesday, February 1, 2022

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, February 1, 2022

**Figure 1: STA 13900+00** – Controls in place and functioning properly.  
BRG: 204°SW (T) LAT: 37.053320 LON: -79.910466 ±643ft ALT: 1093ft



**Figure 2: STA 13928+00** – Controls in place and functioning properly.  
BRG: 249°W (T) LAT: 37.049708 LON: -79.905202 ±32ft ALT: 1057ft



**Figure 3: STA 13948+00** – SSF repair needed.  
BRG: 50°NE (T) LAT: 37.047815 LON: -79.898022 ±98ft ALT: 1042ft



**Figure 4: STA 13981+00** – Controls in place and functioning properly.  
BRG: 112°E (T) LAT: 37.053989 LON: -79.911300 ±9724ft ALT: 1089ft

