



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Tuesday, February 1, 2022	Project Contact:	Brian Clauto		
Spread I: Franklin	St13958-14010 ATWS 1299, 1466 AR-FR-306.02	Weather:	Wet		

	nklin		ATWS	S 1299, 1466 R-306.02		Weather:		Wet				
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling		☐ Clearing/Grubbing ☐ Gra		Grading	ding			Stri	nging/Welding		
	Lowering/B	ackfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	$\boxtimes$	Dor	rmant	
									Yes	No	N/A	
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							erosion and	$\boxtimes$			
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							$\boxtimes$			
	3.	Areas of	offsite	sediment deposition o	observed <sup>e</sup>	?				$\boxtimes$		
<ul> <li><u>Comments:</u> Inspected the following resources: S-KL35, S-KL36, S-KL37, W-EF48</li> <li>ECD's were in place and functioning at the designated crossings.</li> </ul>												
Routine Maintenance: ( <u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Tuesday, February 1, 2022

## FIELD INSPECTION PHOTO LOG



**Project Name:** Mountain Valley Pipeline

Date: Tuesday, February 1, 2022

Figure 1: ESC's in place at designated crossing S-KL35 and W-EF48.



Figure 2: ESC's are in place at designated crossing S-KL36.



Figure 3: ESC's are in place at designated crossing S-KL38.



 <u>Figure 4</u>: ATWS 1466 remains dormant with ESC and stabilization in place.

