

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 27, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15942+00 – 16026+00 Transco Station H-602/H603 Lines	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-H2, W-H3, S-H3, S-H5, W-MM3, S-OO1, S-OO2, S-EF26 and S-H47.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, January 27, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 27, 2022

Figure 1: STA 15950+00 – Controls in place and functioning properly.

BRG: 178°S (T) **LAT:** 36.837214 **LON:** -79.361237 ±32ft **ALT:** 611ft



Figure 2: STA 15967+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 115°SE (T) **LAT:** 36.832741 **LON:** -79.359764 ±12194ft **ALT:** 631ft



Figure 3: STA 15981+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 106°E (T) **LAT:** 36.831626 **LON:** -79.358860 ±23838ft **ALT:** 588ft



Figure 4: STA 16022+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 239°SW (T) **LAT:** 36.825468 **LON:** -79.373872 ±26971ft **ALT:** 624ft

