

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, January 25, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12945+00 – 12982+00 MVP-RO-287 MVP-RO-288	Weather:	Snow

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-Y9, S-Y8 and W-Y1.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, January 25, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, January 25, 2022

Figure 1: STA 12973+00 – Controls in place and functioning properly.
BRG: 109°E (T) LAT: 37.126278 LON: -80.138236 ±3343ft ALT: 2707ft



Figure 2: STA 12976+00 – Controls in place and functioning properly.
BRG: 314°NW (T) LAT: 37.130091 LON: -80.136250 ±98ft ALT: 2693ft



Figure 3: STA 12964+00 – Controls in place and functioning properly.
BRG: 13°N (T) LAT: 37.132743 LON: -80.137531 ±98ft ALT: 2653ft



Figure 4: STA 12946+00 – Controls in place and functioning properly.
BRG: 353°N (T) LAT: 37.136174 LON: -80.138652 ±32ft ALT: 2718ft

