

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, January 24, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13141+00 – 13196+00 MVP-FR-292/292.01	Weather:	Snow

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-D14, S-D13, S-D11 and S-D10.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, January 24, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, January 24, 2022

Figure 1: STA 13141+00 – Controls in place and functioning properly.

BRG: 273°W (T) **LAT:** 37.121101 **LON:** -80.086788 ±98ft **ALT:** 1649ft



13141

Figure 2: Stream S-D13 – Controls in place and functioning properly along stream crossing.

BRG: 59°NE (T) **LAT:** 37.047758 **LON:** -80.015469 ±17267ft **ALT:** 1651ft



S-D13

Figure 3: STA 13163+00 – Controls in place and functioning properly.

BRG: 61°NE (T) **LAT:** 37.070414 **LON:** -79.957724 ±15193ft **ALT:** 1686ft



13163

Figure 4: STA 13193+00 – Controls in place and functioning properly.

BRG: 342°N (T) **LAT:** 37.123862 **LON:** -80.075842 ±32ft **ALT:** 1451ft



13193