



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, January 12, 2022	Project Contact:	Brian Clauto
Spread I: Pittsylvania	St 15500-15585 ATWS 819, 820	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Fellin	g		Clearing/Grubbing		Grading		Trenching	☐ Stringing/Welding		ging/Welding	
	Lowering/E	Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	\boxtimes	Dormant		
									Yes	No	N/A	
	1.		Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?					\boxtimes				
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes			
	3.	Areas of of	ffsite s	sediment deposition of	bserve	d?				\boxtimes		
Comments: Inspected the following resources: S-CC14, S-MM8, W-MM5, S-CC15, S-CC8, S-CC10, S-CC11 ECD's were in place and functioning above the designated crossing. At designated crossing S-MM8 sediment was observed in the stream and turbid water coming from upstream of the ROW. Routine Maintenance: (72-Hour Deadline from Notification) N/A Ineffective Controls: (24-Hour Deadline from Notification) N/A Recommended Corrective Action: N/A												
Deadline: N/A The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												
Inspector Signature:												

Date: Wednesday, January 12, 2022

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Wednesday, January 12, 2022

Figure 1: Designated crossing S-MM8, sediment deposit upstream above ROW.



Figure 2: ATWS 819, ESC's are in place.



Figure 3: St 15511 area is stabilized



Figure 4: Designated stream S-CC8, ESC's are in place.

