

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, January 10, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12414+00 – 12485+00 MVP-MLV-AR-28 MVP-MN-279.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-NN8, S-NN16, S-CD12b and W-KL578.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, January 10, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, January 10, 2022

Figure 1: STA 12484+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 136°SE (T) **LAT:** 37.223450 **LON:** -80.202113 ±16ft **ALT:** 1483ft



Figure 2: STA 12474+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 334°NW (T) **LAT:** 37.226016 **LON:** -80.202059 ±32ft **ALT:** 1380ft



Figure 3: STA 12443+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 295°NW (T) **LAT:** 37.233211 **LON:** -80.198265 ±958ft **ALT:** 1161ft



Figure 4: STA 12471+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 353°N (T) **LAT:** 37.227036 **LON:** -80.202321 ±32ft **ALT:** 1322ft

