

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, February 17, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12760+00 – 12797+00 MVP-RO-282	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF32 and S-EF20.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, February 17, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 17, 2022

Figure 1: STA 12761+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 147°SE (T) LAT: 37.179111 LON: -80.141374 ±164ft ALT: 2904ft



Figure 2: STA 12772+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 193°S (T) LAT: 37.181551 LON: -80.133599 ±6896ft ALT: 2981ft



Figure 3: STA 12781+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 179°S (T) LAT: 37.178437 LON: -80.135868 ±6614ft ALT: 2870ft



Figure 4: STA 12797+00 – Controls in place and functioning properly.
BRG: 21°N (T) LAT: 37.178961 LON: -80.134189 ±6040ft ALT: 2717ft

