

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, February 10, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14861+31 – 14981+55	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-SS8, S-CD8, S-AB8, S-DD3, S-G16, S-G15 and S-G13.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 14989+00: Re-stabilization needed.

Routine Maintenance: (24-Hour Deadline from Notification)

- STA 14888+00: Re-stabilization needed adjacent to S-AB8.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, February 10, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 10, 2022

Figure 1: STA 14888+00 – Re-stabilization needed adjacent to S-AB8.

BRG: 305°NW (T) LAT: 36.970028 LON: -79.651370 ±16ft ALT: 891ft



Restabilize at S-AB8 24hr

14888

Figure 2: STA 14895+00 – Controls in place and functioning properly.

BRG: 117°SE (T) LAT: 36.969723 LON: -79.648921 ±16ft ALT: 894ft



14895

Figure 3: STA 14960+00 – Controls in place and functioning properly.

BRG: 101°E (T) LAT: 36.966548 LON: -79.627420 ±32ft ALT: 935ft



14960

Figure 4: STA 14989+00 – Re-stabilization needed.

BRG: 62°NE (T) LAT: 36.968444 LON: -79.598725 ±15843ft ALT: 955ft



Restabilize 72hr

14989