



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Tuesday, February 22, 2022	Project Contact:	Brian Clauto		
Spread H: Montgomery	St1298-12300, 12154-12150, 12120, 12100-12112 ATWS 1374, 1216, 1217, 1167, 1168 AR-MN276.03, 273, 270.01, 271	Weather:	Wet		

			AR-M	N276.03, 273, 270	0.01, 271								
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling	e Felling		☐ Clearing/Grubbing		☐ Grading		☐ Trenching		Stri	inging/Welding		
	Lowering/B	ackfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗵 Dormant		mant		
									Yes	No	N/A		
	1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes				
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						\boxtimes					
	3.	Areas of o	offsite	sediment depositio	n observe	ed?				\boxtimes			
 <u>Comments:</u> Inspected the following resources: S-C36, W-C12, S-MM11, S-F15, W-F9-PFO, S-F16A&B ECD's were in place and functioning at the designated crossings.]		
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A													
Ineffective Controls: (24-Hour Deadline from Notification) - N/A													
Recommended Corrective Action: N/A													

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Tuesday, February 22, 2022



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 22, 2022

Figure 1: Designated crossing S-C12 & W-C12, ESC's are in place and functioning.



Figure 2: St12300, ESC controls were in place.



Figure 3: Designated crossing S-F15, ESC's are in place and functioning.



Figure 4: St12233+23, ECD's are in place and functioning.

