



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, March 9, 2022	Project Contact:	Brian Clauto
Spread H: Montgomery	St12914-12867+08 ATWS 1236, 1326 AR-Fr	Weather:	Wet

Montgomery		ATWS	S 1236, 1326 r		Weather:		Wet				
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)											
☐ Tree Felling			Clearing/Grubbing		Grading		Trenching		Stri	inging/Welding	
☐ Lowering/Bac	kfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	ı 🗵	Do	rmant	
								Yes	No	N/A	
	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes				
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						\boxtimes				
3. Aı	reas of o	offsite	sediment deposition o	bserve	d?				\boxtimes		
 Comments: Inspected the following resources: S-IJ12, S-KL55, W-KL51, W-EF46, W-KL 49, W-KL48 ECD's were in place and functioning at the designated crossings. 											
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A											
Ineffective Controls: (24-Hour Deadline from Notification) - N/A											
Recommended Corrective Action: N/A											

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: ____

Date: Wednesday, March 9, 2022

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Wednesday, March 9, 2022

 Figure 1: Designated crossing S-IJ12, ESC's are in place and functioning.



Figure 2: St12914, ESC controls were in place.



Figure 3: Designated crossing S-KL55 & W-KL51, ESC's are in place and functioning.



Figure 4: ATWS 1326, ECD's are in place and functioning.

