

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, March 9, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12866+36 – 12915+15 MVP-RO-286	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF46, S-ST9b, W-KL48-PSS-1, W-KL49-PEM, W-KL51-PSS, S-KL55, S-IJ12 and W-MN7-PEM.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, March 9, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, March 9, 2022

Figure 1: MVP-RO-286 – Controls in place and functioning properly.
BRG: 230°SW (T) LAT: 37.144918 LON: -80.135892 ±32ft ALT: 2665ft



Figure 2: STA 12910+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 85°E (T) LAT: 37.119516 LON: -80.137216 ±21305ft ALT: 2686ft



Figure 3: STA 12882+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 16°N (T) LAT: 37.153809 LON: -80.124527 ±13661ft ALT: 2628ft



Figure 4: STA 12877+00 – Controls in place and functioning properly. Area stabilized with erosion matting and straw.
BRG: 17°N (T) LAT: 37.154295 LON: -80.125023 ±7391ft ALT: 2617ft

