

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, March 4, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12971+84 – 13013+53 MVP-RO-288	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Friday, March 4, 2022

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, March 4, 2022

**Figure 1: STA 13011+00** – Controls in place and functioning properly.

**BRG:** 324°NW (T) **LAT:** 37.125924 **LON:** -80.125454 ±16ft **ALT:** 2691ft



**Figure 2: STA 12996+00** – Controls in place and functioning properly.

**BRG:** 157°SE (T) **LAT:** 37.128687 **LON:** -80.130304 ±98ft **ALT:** 2621ft



**Figure 3: STA 12973+00** – Controls in place and functioning properly.

**BRG:** 324°NW (T) **LAT:** 37.126716 **LON:** -80.138085 ±708ft **ALT:** 2702ft



**Figure 4: STA 12981+00** – Controls in place and functioning properly.

**BRG:** 294°NW (T) **LAT:** 37.125610 **LON:** -80.135436 ±11466ft **ALT:** 433ft

