

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, March 18, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14131+21 – 14235+38 MVP-FR-309 MVP-MLV-AR-32	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C8, S-KL51, S-KL52, S-KL54, S-F8, S-HH4, S-C20 and S-C19.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, March 18, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, March 18, 2022

Figure 1: STA 14132+00 – Controls in place and functioning properly.

BRG: 175°S (T) **LAT:** 37.036865 **LON:** -79.856818 ±24553ft **ALT:** 892ft



Figure 2: STA 14155+00 – Controls in place and functioning properly.

BRG: 136°SE (T) **LAT:** 37.057459 **LON:** -79.849669 ±1591ft **ALT:** 966ft



Figure 3: STA 14185+00 – Controls in place and functioning properly.

BRG: 84°E (T) **LAT:** 37.057739 **LON:** -79.838363 ±600ft **ALT:** 962ft



Figure 4: STA 14223+00 – Controls in place and functioning properly.

BRG: 109°E (T) **LAT:** 37.046753 **LON:** -79.840506 ±7624ft **ALT:** 919ft

