

## FIELD INSPECTION REPORT

<b>Project Name:</b>	<b>Mountain Valley Pipeline</b>	<b>Inspector:</b>	<b>Marshall Willis</b>
<b>Inspection Date:</b>	<b>Wednesday, March 16, 2022</b>	<b>Project Contact:</b>	<b>Brian Clauto, Cory Chalmers</b>
<b>Spread I: Franklin County</b>	<b>STA 14758+16 – 14845+68</b>	<b>Weather:</b>	<b>Dry</b>

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MM44, S-MM45, S-MM48, S-H25, S-H24, S-H23, S-HH1, S-A12 and S-A11.

Recommended Corrective Action: N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Wednesday, March 16, 2022

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, March 16, 2022

**Figure 1: STA 14760+00** – Controls in place and functioning properly.

BRG: 144°SE (T) LAT: 36.983617 LON: -79.689529 ±164ft ALT: 1039ft



**Figure 2: STA 14787+00** – Controls in place and functioning properly.

BRG: 93°E (T) LAT: 36.982578 LON: -79.688014 ±34461ft ALT: 899ft



**Figure 3: STA 14793+00** – Controls in place and functioning properly.

BRG: 141°SE (T) LAT: 36.978460 LON: -79.682341 ±12887ft ALT: 878ft



**Figure 4: STA 14844+00** – Controls in place and functioning properly.

BRG: 261°W (T) LAT: 37.010756 LON: -79.736130 ±20521ft ALT: 918ft

