

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, March 28, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12071+80 - 12190+85 MVP-MN-270	Weather:	Dry

AC ⁻	ΓΙ VE STAGE	OF C	CONSTRUCTION: (CI	neck al	I that apply)					
Tree Fell	ing		Clearing/Grubbing		Grading		Trenching		Stri	nging/Welding
Lowering/Backfilling			Final Restoration		Temp. Stabilization		Perm. Stabilization	□ Dormant		rmant
								Yes	No	N/A
1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						erosion and	\boxtimes			
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes			
3. Areas of offsite sediment deposition observed?								\boxtimes		
S-	MM31, S-C29 - STA 1 - STA 1 - STA 1	9, W-0 2133- 2139- 2144-	C6, W-C5, S-C25 and +40 to 12134+70: Re- +00: Re-stabilization n +50 to 12145+00: Re-	S-C24 stabiliza eeded. stabiliza	ation needed.				S-F1	6A/B, S-C36,

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Monday, March 28, 2022



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Monday, March 28, 2022

Figure 1: STA 12133+40 to 12134+70 - Re-stabilization needed.

BRG: 109°E (T) LAT: 37.257372 LON: -80.277255 ±213ft ALT: 1417ft



Figure 2: STA 12139+00- Re-stabilization needed.



Figure 3: **STA 12144+50 to 12145+00** – Re-stabilization needed.

BRG: 281°W (T) LAT: 37.255443 LON: -80.273846 ±16ft ALT: 1437ft



Figure 4: STA 12171+00 - Controls in place and functioning properly. Area stabilized with straw.

BRG: 111°E (T) LAT: 37.237786 LON: -80.264895 ±16259ft ALT: 1427ft

