

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, March 25, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12994+02 – 13012+63 STA 12940+97 – 12973+43 MVP-RO-287/288	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-Y9, S-Y8 and W-Y2.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 12947+00 to 12948+00: Re-stabilization needed.
- STA 12943+00 to 12945+00: Re-stabilization needed.
- STA 12953+00 to 12953+50: Re-stabilization needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Friday, March 25, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, March 25, 2022

Figure 1: STA 12965+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 12°N (T) LAT: 37.124623 LON: -80.142293 ±17962ft ALT: 2701ft



Figure 2: STA 12947+00 to 12948+00 – Re-stabilization needed.
BRG: 300°NW (T) LAT: 37.136997 LON: -80.138890 ±16ft ALT: 2677ft



Figure 3: STA 12943+00 to 12945+00 – Re-stabilization needed.

BRG: 315°NW (T) LAT: 37.137687 LON: -80.139209 ±16ft ALT: 2657ft



Figure 4: STA 12953+00 to 12953+50 – Re-stabilization needed.

BRG: 128°SE (T) LAT: 37.158059 LON: -80.117215 ±27119ft ALT: 2661ft

