

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, March 14, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12446+00 – 12485+00 MVP-MLV-AR-28	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-KL58 and S-CD12b.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, March 14, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, March 14, 2022

Figure 1: STA 12485+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 153°SE (T) LAT: 37.223296 LON: -80.213922 ±541ft ALT: 1272ft



Figure 2: STA 12479+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 341°N (T) LAT: 37.234050 LON: -80.204574 ±541ft ALT: 1258ft



Figure 3: STA 12464+00 – Controls in place and functioning properly. Area stabilized with straw.
BRG: 159°S (T) LAT: 37.228214 LON: -80.203414 ±16ft ALT: 1215ft



Figure 4: Stream S-CD12b – Controls in place and functioning properly around stream crossing.
BRG: 360°N (T) LAT: 37.229833 LON: -80.201264 ±16ft ALT: 1203ft

