



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant		
Inspection Date:	Wednesday, June 15, 2022	Project Contact:	Brian Clauto		
Spread I: Franklin	St 14010-13990 ATWS 1466 AR FR306.02	Weather:	Dry		

Spread I: St 14010-13990 ATWS 1466 AR FR306.02		Weather:		Dry						
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply) ☐ Tree Felling ☐ Clearing/Grubbing ☐ Grading ☐ Trenching ☐ Stringing/Welding										
☐ Tree Felling☐ Lowering/Backfilling☐ Final Grading	_	np. Stabilization	_	Stabilization	 . ⊠		rmant			
					Yes	No	N/A			
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?					\boxtimes					
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?					\boxtimes					
3. Areas of offsite sediment deposition	observed?					\boxtimes				
 <u>Comments:</u> Inspected the following resources: S-KL37, S-KL38, S-KL35 ECD's were in place and functioning at the designated crossings. 										
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A										
Ineffective Controls: (24-Hour Deadline from Notification) - N/A										
Recommended Corrective Action: N/A										

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Wednesday, June 15, 2022



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Wednesday, June 15, 2022

Figure 1: Designated crossing S-KL38, ESC controls were in place.





Figure 3: Designated crossing S-KL37, ESC controls were in place.



<u>Figure 4</u>: Designated crossing S-KL35, ESC controls were in place.

