



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, July 27, 2022	Project Contact:	Brian Clauto
Spread I: Franklin	St 14079-14130 ATWS 1473, 1472 AR FR309.05, 309	Weather:	Rainy

Spread I: Franklin	ΙΔΙW\$ 14/3 14/2 Ι WΔ3thΔr Ι R		Rainy								
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)											
☐ Tree Felling	☐ Clearing/Grubbing	☐ Grad	ding	☐ Trenc	hing		Stri	inging/Welding			
☐ Lowering/Backfill	ing Final Grading	☐ Tem	p. Stabilization	☐ Perm.	Stabilization	n 🗵	Do	rmant			
						Yes	No	N/A			
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes					
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						\boxtimes				
3. Areas of offsite sediment deposition observed?							\boxtimes				
■ <u>Comments:</u> Inspected the following resources: S-KL61, S-KL41											
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A											
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - St14105, SF down near crossing S-KL41.											
Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.											

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Wednesday, July 27, 2022



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 27, 2022

Figure 1: Designated crossing S-KL61, ESC controls were in place.



Figure 2: St14094, ECD's are in place and stabilized.



Figure 3: Designated crossing S-KL41, Silt fence is down at St14105.



Figure 4: St14120, ECD's are in place and stabilized.

