

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, April 11, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12373+76 - 12448+00 MVP-MN-279.02	Weather:	Dry

<u>ACTI</u>	VE STAGE	OF C	CONSTRUCTION: (C	heck al	I that apply)						
Tree Fellin	g		Clearing/Grubbing		Grading		Trenching		Stri	nging/Welding	
Lowering/E	Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	\boxtimes	Dormant		
								Yes	No	N/A	
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes			
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes			
3. Areas of offsite sediment deposition observed?									\boxtimes		
 Comments: Inspected the following resources: SNN19, W-NN8 and S-NN16. Routine Maintenance: (72-Hour Deadline from Notification) STA 12441+50: Re-stabilization needed. Recommended Corrective Action: Maintain and install all controls per the approved PSS&S. 											

<u>Deadline:</u> Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Monday, April 11, 2022



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, April 11, 2022

Figure 1: **STA 12424+00** – Controls in place and functioning properly.

BRG: 160°S (T) LAT: 37.235872 LON: -80.199556 ±29ft ALT: 1178ft



<u>Figure 2:</u> **STA 12433+00** – Controls in place and functioning properly.

BRG: 317°NW (T) LAT: 37.233571 LON: -80.198999 ±439ft ALT: 1172ft



<u>Figure 3</u>: **STA 12440+00** – Controls in place and functioning properly.

BRG: 208°SW (T) LAT: 37.232391 LON: -80.198972 ±36ft ALT: 1261ft



Figure 4: STA 12441+50 (ATWS 727) – Re-stabilization needed.

