

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, April 5, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12007+33 – 12072+84 MVP-MN-268.01/270	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G38, S-G40, S-G39 and S-PP23.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, April 5, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 5, 2022

Figure 1: STA 12071+00 – Controls in place and functioning properly.

BRG: 338°N (T) LAT: 37.259090 LON: -80.298018 ±98ft ALT: 2007ft



12071

Figure 2: STA 12053+00 – Controls in place and functioning properly.

BRG: 354°N (T) LAT: 37.261873 LON: -80.302514 ±32ft ALT: 2313ft



12053

Figure 3: STA 12044+00 – Controls in place and functioning properly.

BRG: 112°E (T) LAT: 37.263451 LON: -80.304160 ±2775ft ALT: 2328ft



12044

Figure 4: STA 12028+00 – Controls in place and functioning properly.

BRG: 294°NW (T) LAT: 37.265551 LON: -80.310240 ±164ft ALT: 1997ft



12028