



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, July 25, 2022	Project Contact:	Brian Clauto
Spread H:		Weather:	Dry

	inono												
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
☐ Tree Felling		☐ Clearing/Grubbing			Grading		☐ Trenching		☐ Stringing/\				
	☐ Lowering/Backfilling ☐		Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗵 Dorm		mant			
									Yes	No	N/A		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes					
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes					
Areas of offsite sediment deposition observed?									\boxtimes				
 Comments: Inspected the following resources: W-008 ECD's were in place and functioning at the designated crossings. Routine Maintenance: (72-Hour Deadline from Notification) N/A Ineffective Controls: (24-Hour Deadline from Notification) N/A Recommended Corrective Action: N/A 													
_													
<u>Deadline:</u> N/A													

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Monday, July 25, 2022

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline Date: Monday, July 25, 2022

 Figure 1: LY049 perimeter controls remain in place and functioning.



<u>Figure 2</u>: Construction road/ entrance of LY049 remains in place and functioning.



Figure 3: PY06 Fuel protection in place.



■ Figure 4: Wetland W-008 within PY06 remains protected.

