

## FIELD INSPECTION REPORT

|                              |                                              |                  |                             |
|------------------------------|----------------------------------------------|------------------|-----------------------------|
| Project Name:                | Mountain Valley Pipeline                     | Inspector:       | Marshall Willis             |
| Inspection Date:             | Wednesday, April 20, 2022                    | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread I:<br>Franklin County | STA 14333+27 – 14411+04<br>MVP-FR-313.01/315 | Weather:         | Dry                         |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?                                                                                                                                  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-A36, S-A38, S-A40, W-DD1 and S-A41.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Wednesday, April 20, 2022

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, April 20, 2022

**Figure 1: STA 14350+00** – MVP actively replacing and maintaining controls and re-stabilizing.



**Figure 2: STA 14370+00** – Controls in place and functioning properly.



**Figure 3: STA 14385+00** – Controls in place and functioning properly.



**Figure 4: STA 14399+00** – Controls in place and functioning properly.

