

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis			
Inspection Date:	Monday, July 25, 2022	Project Contact:	Brian Clauto, Cory Chalmers			
Spread I: Franklin County	STA 13892+45 - 14010+05 MVP-FR-305/306.02	Weather:	Dry			

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling		Clearing/Grubbing		Grading		Trenching		Strir	nging/Welding		
	Lowering/Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	□ Dormant				
								Yes	No	N/A		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes				
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes				
3. Areas of offsite sediment deposition observed?								\boxtimes				
	<u>Comments:</u> In	specte	ed the following resource	ces: S-	·II12, S-CD1, W-CD1, \	W-EF4	48, S-KL35, S-KL37	and S-I	<l38.< td=""><td></td></l38.<>			
	<u>Deadline:</u> N	<u>'A</u>										
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												
	Inspector Sig	natur	e: Marshall	1/1	Willist .							
	Date: Mond	ay, J	uly 25, 2022									



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, July 25, 2022






Figure 2: STA 13947+00— Controls in place and functioning properly.




Figure 3: **STA 13981+00** – Controls in place and functioning properly.



Figure 4: **STA 13995+00** – Controls in place and functioning properly.

