

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, July 22, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13748+30 - 13846+00 MVP-FR-302	Weather:	Dry

	ACTIVE STAGE	OF (CONSTRUCTION: (Ch	ock al	I that apply)						
	Tree Felling		Clearing/Grubbing		Grading		Trenching		Strir	nging/Welding	
	Lowering/Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	☑ Dormant			
								Yes	No	N/A	
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?										
	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes			
3. Areas of offsite sediment deposition observed?								\boxtimes			
	Comments: Inspected the following resources: S-EF7, S-EF12, S-MM42, S-RR15, S-D23, S-D22 and S-D20.										
	Deadline: N/	<u>4</u>									
	The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.										
	Inspector Sigr	atur	e: Marshall	11/1	Willist .						
	Date: Friday	, Jul	y 22, 2022								



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, July 22, 2022

Figure 1: **STA 13750+00** – Controls in place and functioning properly.



Figure 2: STA 13775+00 – Controls in place and functioning properly.



<u>Figure 3</u>: **STA 13787+00** – Controls in place and functioning properly.



<u>Figure 4</u>: **STA 13815+00** – Controls in place and functioning properly.

