

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, August 2, 2022	Project Contact:	Brian Clauto
Spread H: Franklin	ATWS 1251, 1483, 1482 AR FR292, 292.02 ST13142-13188	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
☐ Tree Felling			☐ Clearing/Grubbing			☐ Grading		☐ Trenching			Str	inging/Welding
	Lowering/B	ackfilling		Final Grading		Temp. Stab	oilization		Perm. Stabilization	n 🗵 Dormant		rmant
										Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?									\boxtimes		
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?										
	3.	Areas of o	ffsite	sediment deposition	observe	ed?					\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-D11, S-D10, S-D9, W-D4, S-D14 ECD's were in place and functioning at the designated crossings. 												
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Tuesday, August 2, 2022



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Tuesday, August 2, 2022

 <u>Figure 1</u>: Designated crossing S-D14 on AR FR 292, ECD's are in place.



Figure 2: Designated crossing S-D11, ECD's are in place.



Figure 3: St13147+25 ECD's and stabilization are in place.



Figure 4: St13163 ECD's and stabilization are in place.

