

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, August 2, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13140+00 - 13195+00 MVP-FR-292/.01/.02	Weather:	Wet

						•		•			
	ACTIV	VE STAGE	OF C	CONSTRUCTION: (CI	neck al	ll that apply)					
	Tree Felling	g		Clearing/Grubbing		Grading		Trenching		Stri	nging/Welding
	Lowering/E	Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	on 🗵 Dormant		
									Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes		
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes		
3. Areas of offsite sediment deposition observed?								\boxtimes			
	Con	nments: Ins	specte	ed the following resour	ces: S	-D14, S-D13 and S-D1	1.				
	Deac	<u>lline: N/</u>	<u>A</u>								
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.											
	Inspe	ector Sigr	natur	e: Manhae	I IX	Willia					
	Date	: Tuesd	lay, A	August 2, 2022							



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 2, 2022

<u>Figure 1</u>: **STA 13142+00** – Controls in place and functioning properly.



<u>Figure 2:</u> **STA 13150+00** – Controls in place and functioning properly.



<u>Figure 3</u>: **STA 13163+00** – Controls in place and functioning properly.



Figure 4: **STA 13188+00** – Controls in place and functioning properly.

