

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, January 25, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13410+56 – 13425+00 MVP-FR-293.02 MVP-FR-303.01	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling

☐ Clearing/Grubbing

☐ Grading

☐ Trenching

☐ Stringing/Welding

☐ Lowering/Backfilling

☐ Final Restoration

☐ Temp. Stabilization

☐ Perm. Stabilization

☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ1, S-IJ2, W-IJ1, S-IJ3, W-IJ2-PSS and S-IJ4.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, January 25, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, January 25, 2023

Figure 1: MVP-FR-293.02 – Controls in place and functioning properly along access road crossing.



Figure 2: STA 13423+00 – Controls in place and functioning properly.



Figure 3: STA 13416+00 – Controls in place and functioning properly.



Figure 4: MVP-FR-303.01 – Controls in place and functioning properly.

