

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, December 29, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14649+67 – 14758+07	Weather:	Wet

1 I U	intim Count	·y									
	<u>ACTI</u>	VE STAGE	OF C	ONSTRUCTION: (C	heck a	ll that apply)					
	Tree Felling		☐ Clearing/Grubbing			Grading		Trenching		Stri	inging/We l ding
	Lowering/B	g/Backfilling \square Final Restoration \square Temp. Stabilization \square Perm. Stabilizatio		n 🗵	Doi	rmant					
									Yes	No	N/A
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 						erosion and	\boxtimes			
							\boxtimes				
	3.	Areas of o	ffsite s	sediment deposition of	observe	ed?				\boxtimes	
Comments: Inspected the following resources: S-H40, W-H17, S-H37, W-H16, S-H36, S-H34, W-H14, S-H32, W-H11, W-A8, S-A18, S-A19/H26, S-A30, S-H27 and S-A22. Recommended Corrective Action: N/A										W-H11, W-	
		Iline: N//	_	rtive action deadline da	e annlie	s to all conditions noted c	ın this ı	renort unless otherwise	noted	If lister	1
	conditi	on(s) current	ly cons	stitute non-compliance	and/or co	orrective actions are not o	complet	ted by the deadline, oth	ner enfo	cemer	nt
	Inspe	ector Sign	ature	e: Manha	U K	Willis?					
	Date	Thurse	day, l	December 29, 202	2						



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Figure 1: STA 14663+00 - Controls in place and functioning

Date: Thursday, December 29, 2022

Figure 2: STA 14698+00 – Controls in place and functioning properly.



<u>Figure 3</u>: **STA 14739+00** – Controls in place and functioning properly.



Figure 4: STA 14756+00 — Controls in place and functioning properly.

