

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, December 8, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14333+27 - 14411+09 MVP-FR-313.01/314/315	Weather:	Wet

	<u>ACTI</u>	<u>/E STAGE</u>	OF C	CONSTRUCTION: (C	neck al	ll that apply)					
	Tree Felling	g		Clearing/Grubbing		Grading		Trenching		Stri	nging/Welding
	Lowering/B	ackfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	on 🗵 Dormant		
									Yes	No	N/A
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes		
	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes			
	3. Areas of offsite sediment deposition observed?							\boxtimes			
<u>Comments:</u> Inspected the following resources: S-A36, S-A38, S-A40, W-DD1 and S-A41.											
	Rec	ommend	ed Co	orrective Action: N	/A						
	Dead	lline: N/	<u>A</u>								
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.											
	Inspe	ector Sigr	natur	e: Manhai	I K	Millio					
	Date	Thurs	day,	December 8, 2022							



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Figure 1: STA 14334+00 - Controls in place and functioning

Date: Thursday, December 8, 2022



Figure 2: STA 14345+00 – Controls in place and functioning properly.



<u>Figure 3</u>: **STA 14371+00** – Controls in place and functioning properly.



<u>Figure 4</u>: **STA 14402+00** – Controls in place and functioning properly.

