



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, October 31, 2022	Project Contact:	Brian Clauto
Spread I: Franklin	ATWS 619, 350 LY 047, 034, 032, 033 AR FR32/312, 313	Weather:	Rainy

Spread I: Franklin			ATWS 619, 350 LY 047, 034, 032, 033 AR FR32/312, 313				Weather:			Rainy				
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)														
	Tree Fellin	ng Clearing/Grubbing Grading Trenching		hing		Stri	nging/Welding							
	Lowering/E	Backfilling		Final Gradin	9 🗆	Ter	p. Stabilization 🔲 Perm. Stabilization				\boxtimes	Dormant		
											Yes	No	N/A	
	1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								and	\boxtimes			
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes				
3. Areas of offsite sediment deposition observed?										\boxtimes				
 <u>Comments:</u> Inspected the following resources: S-C19 ECD's were in place and functioning at the designated crossing.]			
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A														
Ineffective Controls: (24-Hour Deadline from Notification) - N/A														
Recommended Corrective Action: N/A														
													╛	

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Monday, October 31, 2022

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Monday, October 31, 2022

Figure 1: ECD's in place and functioning at LY047.



Figure 2: Designated crossing S-C19, ESC controls were in place.



 <u>Figure 3</u>: Pollution prevention controls in place and functioning at LY047.



 <u>Figure 4</u>: Pollution prevention controls in place and functioning at LY047.

