

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis		
Inspection Date:	Thursday, October 6, 2022	Project Contact:	Brian Clauto, Cory Chalmers		
Spread I: Franklin County	STA 13644+82 – 13690+91 STA 13826+95 – 13852+46 MVP-FR-302/303.01	Weather:	Dry		

Fra	nklin County	MVP-FR-302/303.01											
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling	☐ Clearing/Grubbing	bing 🗌 Grading 🔲 Trend		enching		Strir	nging/Welding					
	Lowering/Backfilling	☐ Final Restoration	☐ Tem	np. Stabilization \Box Perm. Stabilization			\boxtimes	Dori	mant				
							Yes	No	N/A				
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes						
	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						\boxtimes						
	3. Areas of	offsite sediment deposition ob	served?					\boxtimes					
	<u>Comments:</u> In	Inspected the following resourc	ces: S-GH3,	S-GH4, S-GH2 S	S-E29, S-	E28, S-C14 and 9	S-C16.						
	<u>Deadline:</u> N	N/A											
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.													
	Inspector Sig	gnature: Makshall	I Will	<u> </u>									
	Date: Thur	rsday, October 6, 2022											



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, October 6, 2022



Figure 2: STA 13689+00 – Controls in place and functioning properly.



<u>Figure 3</u>: **STA 13828+00** – Controls in place and functioning properly.



Figure 4: **STA 13852+00** – Controls in place and functioning properly.

