

## FIELD INSPECTION REPORT

| Project Name:               | Mountain Valley Pipeline              | Inspector:       | Marshall Willis             |
|-----------------------------|---------------------------------------|------------------|-----------------------------|
| Inspection Date:            | Tuesday, January 24, 2023             | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread H:<br>Roanoke County | STA 12964+64 - 12982+00<br>MVP-RO-288 | Weather:         | Wet                         |

|  | ACTIVE STAGE  | OF C     | ONSTRUCTION: (Ch           | ieck al  | I that apply)  |          |                         |              |             |               |
|--|---|----------|----------------------------|----------|--|----------|-------------------------|--------------|-------------|---------------|
|  | Tree Felling  |          | Clearing/Grubbing          |          | Grading  |          | Trenching               |              | Stri        | nging/Welding |
|  | Lowering/Backfilling  |          | Final Restoration          |          | Temp. Stabilization  |          | Perm. Stabilization     | on 🗵 Dormant |             |               |
|  |   |          |                            |          |  |          |                         | Yes          | No          | N/A           |
|  | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       |          |                            |          |  |          |                         | $\boxtimes$  |             |               |
|  | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? |          |                            |          |  |          | $\boxtimes$             |              |             |               |
|  | 3. Areas of o   | offsite  | sediment deposition ob     | oserve   | d?   |          |                         |              | $\boxtimes$ |               |
| <u>Comments:</u> Inspected the following resources: S-KL4, W-Q11, W-KL1 and W-IJ10. <u>Recommended Corrective Action</u> : N/A |   |          |                            |          |  |          |                         |              |             |               |
|  | Deadline: N/  |          | ctive action deadline date | applie   | s to all conditions noted o  | n this r | eport unless otherwise  | e noted. I   | f listed    |               |
|  | condition(s) currer   | itly con | stitute non-compliance ar  | nd/or co | orrective actions are not on the about the compliance on the about | omplet   | ed by the deadline, oth |              |             |               |
|  | Inspector Sig   | natur    | e: Marshau                 | I K      | Willist .  |          |                         |              |             |               |

Date: Tuesday, January 24, 2023

FIELD INSPECTION PHOTO LOG



## **Project Name: Mountain Valley Pipeline**

Date: Tuesday, January 24, 2023

<u>Figure 1</u>: **Stream S-KL4** – Controls in place and functioning properly along access road crossing.



<u>Figure 2:</u> **STA 12976+00** – Controls in place and functioning properly.



<u>Figure 3</u>: **STA 12976+00** – Controls in place and functioning properly.



Figure 4: MVP-R0-288 – Controls in place and functioning properly.

