

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis	
Inspection Date:	Monday, January 23, 2023	Project Contact:	Brian Clauto, Cory Chalmers	
Spread H: Franklin County	STA 13136+00 - 13196+71 MVP-FR-292/.02 MVP-MLV-AR-29	Weather:	Wet	

Fra	nklin County	MVP-MLV-AR-29	Troutilo.					
	ACTIVE STAG	E OF CONSTRUCTION: (Check all the	nat apply)					
	Tree Felling	☐ Clearing/Grubbing ☐ C	Grading	☐ Trench	ning		Stringing	g/Welding
	Lowering/Backfilling	☐ Final Restoration ☐ 7	Гетр. Stabilization	☐ Perm.	Stabilization	\boxtimes	Dormant	[
					Ye	s N	No N/A	
		rols installed and implemented in acco t control plan and stormwater manage		oved erosion	and \boxtimes			
		ontrol measures properly maintained in dengineering practices and, where ap						
	3. Areas of	offsite sediment deposition observed?	,				\boxtimes	
		nspected the following resources: S-D ded Corrective Action: N/A	14, S-D17, S-D13, S-	D12, W-D7-F	PEM, S-D11 S-D	8 and	I S-D10.	
		I/A ed corrective action deadline date applies to	o all conditions noted on	this report unl	ess otherwise note	ed. If li	isted	
	condition(s) curre	ently constitute non-compliance and/or corressued to the entity responsible for ensuring	ective actions are not co	mpleted by the				
	Inspector Sig	gnature: Marshall Wi	Midia					

Date: Monday, January 23, 2023



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, January 23, 2023

Figure 1: **STA 13140+00** – Controls in place and functioning properly.



Figure 2: STA 13159+00 – Controls in place and functioning properly.



<u>Figure 3</u>: **STA 13163+00** – Controls in place and functioning properly.



<u>Figure 4</u>: **STA 13188+00** – Controls in place and functioning properly.

