

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, December 7, 2022	Project Contact:	Brian Clauto
Spread H: Montgomery	ATWS 645, 645a, 727, 725, 1222 LY049 AR MN 279	Weather:	Rainy

		71 X 1V1	N 213								
ACTIVE ST	AGE OF CONST	RUC	TION: (Check all that	apply)	ı						
☐ Tree Felling			☐ Clearing/Grubbing ☐ Gra		Grading	☐ Trenching			☐ Stringing/Weld		
☐ Lower	Lowering/Backfilling		Temp. Stabilization		Perm. Stabilization	□ Dormant					
								Yes	No	N/A	
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes					
2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes			
3.	 Areas of offsite sediment deposition observed? 								\boxtimes		
Routine Maintenance: (72-Hour Deadline from Notification) - N/A Ineffective Controls: (24-Hour Deadline from Notification) - N/A Recommended Corrective Action: N/A											
<u>Deadline: N/A</u> The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.											

Inspector Signature:

Date: Wednesday, December 7, 2022

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Wednesday, December 7, 2022

Figure 1: Controls remain in place at ATWS 645A.



 Figure 2: LY 049 construction entrance remains in place and functioning.



Figure 3: LY049, pollution prevention remains in place and functioning.



Figure 4: ECD remains in place and functioning at LY049.

