

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, April 25, 2023	Project Contact:	Brian Clauto
Spread H: Franklin	AR FR 290 Sta 12995-13067 ATWS 954, 344	Weather:	Dry

Hu	IKIIII		ATW	S 954, 344								
ACTI	VE STAGE	OF CONS	TRUC	CTION: (Check all	that apply)	1						
☐ Tree Felling			Clearing/Grubbing		☐ Grading			☐ Trenching		☐ Stringing/Welding		
	Lowering/E	Backfilling		Final Grading		Tem	np. Stabilization $\ \square$ Perm. Stabilization			n 🗵	Dor	mant
										Yes	No	N/A
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes				
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?										
	3.	Areas of	offsite	sediment deposition	on observe	d?					\boxtimes	
■ Comments: Inspected the following resources: S-G24, S-H1, S-G26, S-G27. S-RR18, S-RR6 ■ ECD's were in place and functioning at the designated crossings. Routine Maintenance: (72-Hour Deadline from Notification) - N/A Ineffective Controls: (24-Hour Deadline from Notification) - N/A Recommended Corrective Action: N/A												
Deadline: N/A The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible ensuring compliance on the above project.										•		
onoui	ing compliant	on the ab	ove pre	<i>-78</i> 1	u I	_						

Inspector Signature: _____

Date: Tuesday, April 25, 2023



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Tuesday, April 25, 2023

Figure 1: Sta 13015, ECD's are in place and functioning.



Figure 2: Designated crossings S-H1, ESC measures in place.



Figure 3: Sta 13040, ECD's are in place and functioning.



Figure 4: Designated crossing S-G24, ESC measures in place.

