

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis			
Inspection Date:	Wednesday, May 24, 2023	Project Contact:	Brian Clauto, Cory Chalmers			
Spread I: Franklin County	STA 14062+17 - 14171+36 MVP-FR-309.05/309.06	Weather:	Dry			

	man ooun	.,		1 11 000100/000100								
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	☐ Tree Felling		☐ Clearing/Grubbing			☐ Grading		☐ Trenching		Stri	nging/Welding	
	Lowering/B	ng/Backfilling \square Final Restoration \square Temp. Stabilization \square Perm. Stabilization		Perm. Stabilization	⊠ Dormant							
									Yes	No	N/A	
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 								\boxtimes			
									\boxtimes			
	3.	Areas of o	ffsite	sediment deposition c	bserve	d?				\boxtimes		
	<u>Com</u>	<u>nments:</u> Ins	specte	ed the following resou	ces: S	-EF48, W-EF51, S-KL	61, S-ł	<l41, an<="" p="" s-c8,="" s-f4=""></l41,>	d S-KL	51.		
	Dead	lline: N/	<u>A</u>									
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.												
	Inspe	ector Sigr	natur	e: Makshau	I K	Pallis						
	Date	Wedn	esda	y, May 24, 2023								



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Figure 1: STA 14072+00 - Controls in place and functioning

Date: Wednesday, May 24, 2023

broberly.

| 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.1. | 1.

Figure 2: STA 14110+00 – Controls in place and functioning properly.



<u>Figure 3</u>: **STA 14140+00** – Controls in place and functioning properly.



<u>Figure 4</u>: **STA 14165+00** – Controls in place and functioning properly.

