

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, June 30, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12119+17 - 12155+00 MVP-MN-273	Weather:	Dry

11101	nigomicity o	ounty		WII 275							
	ACTIV	VE STAGE	OF C	ONSTRUCTION: (C	neck al	ll that apply)					
	Tree Felling		☐ Clearing/Grubbing			☐ Grading		☐ Trenching		Stri	nging/Welding
	Lowering/B	Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	n 🗵 Other		
									Yes	No	N/A
	 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? 								\boxtimes		
									\boxtimes		
	3. Areas of offsite sediment deposition observed?									\boxtimes	
	<u>Com</u>	n <u>ments:</u> Ins	specte	ed the following resour	ces: W	/-C12, S-C36, W-C11,	S-MM	31, S-C29, W-C6 an	d W-C	5.	
	Dead	<u>lline:</u> N/	<u>A</u>								
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.											
	Inspe	ector Sigr	natur	e: Manhai	II.	Pillis					
	Date	: Friday	, Jur	ne 30, 2023							



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, June 30, 2023



Figure 2: STA 12150+00 – Controls in place and functioning properly.

STA 12150+00 – Controls in place and functioning properly.

STA 12150+00 – Controls in place and functioning properly.

STA 12150+00 – Controls in place and functioning properly.

<u>Figure 3</u>: **Stream S-C29**— Controls in place and functioning properly. Recently replaced timber mat crossing and perimeter controls.



<u>Figure 4</u>: **STA 12125+00** – Crews clearing brush, installing new timber mats and CFS.

