

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, June 20, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Franklin County	MVP-FR-293.01 MVP-FR-292 MVP-RO-281/281.01/281.02	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling

☐ Clearing/Grubbing

☐ Grading

☐ Trenching

☐ Stringing/Welding

☐ Lowering/Backfilling

☐ Final Restoration

☐ Temp. Stabilization

☐ Perm. Stabilization

☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF32, S-D17, S-D14 and S-II4.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, June 20, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, June 20, 2023

Figure 1: MVP-RO-281 – Controls in place and functioning properly.



Figure 2: MVP-RO-281 – Controls in place and functioning properly.



Figure 3: Stream S-II4 – Controls in place and functioning properly along stream crossing.



Figure 4: MVP-FR-293.01 – Controls in place and functioning properly.

