



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, June 28, 2023	Project Contact:	Brian Clauto
Spread I: Franklin	Sta 13894-13960 ATWS 697, 698a, 698b, 698c, 1299a	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)											
	Tree Fellin	g		Clearing/Grubbing		Grading		Trenching		Strin	ging/Welding
	Lowering/E	Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	n 🗵 Dormant		nant
									Yes	No	N/A
	1.			alled and implemented plan and stormwater n		cordance with the approper	oved e	erosion and	\boxtimes		
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes		
	3.	Areas of of	fsite s	sediment deposition ob	serve	d?				\boxtimes	
■ Comments: Inspected the following resources: S-II2, S-CD1, W-CD1 ■ ECD's were in place and functioning at the designated crossing. Routine Maintenance: (72-Hour Deadline from Notification) - N/A Ineffective Controls: (24-Hour Deadline from Notification) - N/A Recommended Corrective Action: N/A											
Deadline: N/A The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project. Inspector Signature:											

Wednesday, June 28, 2023

Date:



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, June 28, 2023

Figure 1: Sta 13903+85, ESC controls are in place.



Figure 2: Designated crossing S-II2, ECD's are in place.



Figure 3: Sta 13921, ECD's and stabilization remains in place.



<u>Figure 4</u>: Designated crossing S-CD1 & W-CD1, ECD's are in place.

