

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, July 20, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13632+25 – 13690+91	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☒ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Other

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-E28, S-GH3, S-GH4, S-GH2 and S-E29.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 13662+00: Repair CFS ET and key into WB to prevent discharge from bypassing ET.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, July 20, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 20, 2023

Figure 1: STA 13662+00 – Repair CFS ET and key into WB to prevent discharge from bypassing ET.



Figure 2: STA 13690+00 – Controls in place and functioning properly.



Figure 3: Stream S-E29 – Controls in place and functioning properly along stream crossing.



Figure 4: STA 14636+00 – Controls in place and functioning properly.

