

## FIELD INSPECTION REPORT

|                                |                                       |                  |                             |
|--------------------------------|---------------------------------------|------------------|-----------------------------|
| Project Name:                  | Mountain Valley Pipeline              | Inspector:       | Marshall Willis             |
| Inspection Date:               | Tuesday, July 11, 2023                | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread H:<br>Montgomery County | STA 12119+17 – 12140+24<br>MVP-MN-272 | Weather:         | Dry                         |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☒ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Other

- |    |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?                                                                                                                                  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-C12, S-C36, W-C11, S-MM31 and S-C29.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Tuesday, July 11, 2023

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, July 11, 2023

**Figure 1: STA 12130+00** – Controls in place and functioning properly.



**Figure 2: Stream S-C29** – Controls in place and functioning properly.



**Figure 3: Stream S-C29** - Controls in place and functioning properly.



**Figure 4: Stream S-C29** - Controls in place and functioning properly.

