



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, August 24, 2023	Project Contact:	Brian Clauto
Spread H: Roanoke	Sta 12705-12716+55 ATWS 1627, 955, 955A AR RO280	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
☐ Tree Felling			☐ Clearing/Grubbing ☒ Grading		Grading	☐ Trenching			☐ Stringing/Weldi			
	Lowering/Backfilling Final Grading		Final Grading		Temp. Stabilization		Perm. Stabilization	n 🏻 Reso		urce Crossing		
									Yes	No N	N/A	
	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes				
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes				
	3.	Areas of of	fsite s	sediment deposition ob	serve	d?				\boxtimes		
Routine Maintenance: (72-Hour Deadline from Notification) - ATWS 1627, area near the perimeter of workspace are denuded and require stabilization. Ineffective Controls: (24-Hour Deadline from Notification) - N/A. Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.												
Deadline: Within 72-Hour of Notification The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project. Inspector Signature:												

Thursday, August 24, 2023

Date:

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline

Date: Thursday, August 24, 2023

Figure 1: Designated crossing S-Y14, ECD's are in place.



<u>Figure 2</u>: Above designated crossings S-Y13 & S-Y14, ECD's are in place.



Figure 3: ATWS 1627, denuded area requires stabilization.



■ Figure 4: ATWS 1627, denuded area requires stabilization.

