

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, August 18, 2023	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Roanoke County</b>	STA 12866+00 – 12870+00 STA 12773+00 – 12777+00 MVP-RO-282 MVP-RO-283 MVP-RO-280	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |   |  |   |   |
|---|---|--|---|---|
| <input type="checkbox"/> Tree Felling         | <input checked="" type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading  | <input checked="" type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding            |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration            | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization  | <input checked="" type="checkbox"/> Resource Crossing |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF46 and S-EF33

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Friday, August 18, 2023

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, August 18, 2023

**Figure 1: STA 12867+50** – Installing timber matting through W-EF46.



**Figure 2: MVP-RO-283** – Controls in place and functioning properly.



**Figure 3: Stream S-EF33** – Controls in place and functioning properly.



**Figure 4: Stream S-EF33** – Dewatering structure in place and functioning properly.

