

## **FIELD INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, September 14, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14649+47 – 14712+33	Weather:	Dry

ACTI	IVE STAGE	OF C	CONSTRUCTION: (C	heck all	that apply)					
Tree Felling		☐ Clearing/Grubbing			☐ Grading		☐ Trenching		☐ Stringing/Weldir	
Lowering/l	Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	Resource Crossin		
								Yes	No	N/A
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								$\boxtimes$		
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							$\boxtimes$			
3. Areas of offsite sediment deposition observed?									$\boxtimes$	
Min	nimum Stan - STA 1	idard 4695- ntrols	1: ( <u>7 Day Deadline</u> fr	rom Nota abilize do from No	ormant areas within 7 of		, W-H16, W-H15, S-H	H36, S-	Н34 ғ	and W-H14.

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

Date: Thursday, September 14, 2023



## **FIELD INSPECTION PHOTO LOG**

Project Name: **Mountain Valley Pipeline**  Date: Thursday, September 14, 2023

Figure 1: STA 14694+00 - Remove and properly dispose of coating materials 36°59'16"N, 79°42'37"W ±13ft ▲ 955ft E @121°SE



Figure 3: Stream S-H38- Controls in place and functioning properly along boring of S-H38.



Figure 4: Stream S-H38- Controls in place and functioning properly along boring of S-H38.

